

## Conversion Table

Convert From Unit	Multiply By	Convert to Unit
PSI (Pounds per Square Inch)	2.307	Feet of Head
Feet of Head	0.4335	PSI (Pounds per Square Inch)
Inches of Mercury	0.4912	PSI (Pounds per Square Inch)
PSI (Pounds per Square Inch)	2.036	Inches of Mercury
Bars	14.5	PSI (Pounds per Square Inch)
PSI (Pounds per Square Inch)	0.0689	Bar
Inches	0.03937	Millimeters
Millimeters	25.4	Inches
Feet	0.3048	Meters
Meters	3.281	Feet